CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM		Page 1 of 3
Sewershed: JONES FALLS	Company: REI/DRAYCO	Date: 06/18/08
Test to be Performed: SMOKE	Ground Condition: DRY	Supervisor: ER
Manhole ID: S37QQ_009MH	Test ID: 0994-352	Notifications Made:_X__ (Residents, Fire, 311)

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM		Page 2 of 3
Sewershed: **JONES FALLS**	Company: REI/DRAYCO	Date: 06/18/2008
Test to be Performed: Smoke: __X____ Dyed Water: _____	Ground Condition: Dry: _X____ Damp: ___ Wet: ___	Supervisor:___E.R.__
Manhole ID: S37QQ_009MH	Test ID: 0994-352	Notifications Made:____X____ (Residents, Fire, 311)

Field Sketch: (Show all Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

Defect No.	Address	Source Type	Location	Sector	Drainage Area	Severity	Photo Number
1	612 BARTLETT AVE.	03	08	01	1	03	352_OB01-01

OBSERVATION CODES

	Source Type	Location	Sector	Severity		Source Type	Location		
01	Main Sewer	Paved Concrete	Public	No Smoke	10	MH Frame S	Non-Paved		
02	Service Line	Paved Asphalt	Private	Trace	11	Storm Drain	Field/Woods		
03	Cleanout	Paved Other		Moderate	12	Catch Basin/	Alley		
04	Downspout	Driveway		Major	13	Storm Manh	Golf Course		
05	Area Drain	Sidewalk			14	Storm Ditch	Other		
06	Driveway Drain	Curb			15	Excavation			
07	Stairwell Drain	Yard- Front			16	Other			
08	Foundation Drain	Yard-Back							
09	Building Interior	Yard- Side							

CITY OF BALTIMORE
SMOKE TESTING OBSERVATION SUMMARY
JONES FALLS SEWERSHED
BALTIMORE CITY PROJECT 994
REI/DRAYCO

Unique Test ID: 352	Date: 06/18/2008	Basin: JF-19
Defect No: 1	Supervisor: E.R.	Dye Test Recommended: N
House No: 612	Street Name: BARTLETT	Street Type: AVE
Source Type: 03	Location: 08	Severity: 03
Sector: 02	Drainage Area: 1	

Comments: CLEAN OUT - AT GRADE. MISSING CAP.

SMOKE TEST PHOTOGRAPHS

Photograph No: OB01-01
Filename: 0994-352_OB01-01.jpg